


CUSTOM COOLER, INC



NOTE:

FOR ALL MECHANICALLY FASTENED ANCHORS,
SPECIAL INSPECTION MAY BE REQUIRED,
VERIFY WITH LOCAL BUILDING OFFICIAL.

CUSTOM COOLER CLP 600 SERIES
FREEZER WALL PANEL CONNECTION TO SLAB
WITH THERMAL BREAK