



FOR ALL MECHANICALLY FASTENED ANCHORS, SPECIAL INSPECTION MAY BE REQUIRED, VERIFY WITH LOCAL BUILDING OFFICIAL.

CUSTOM COOLER CLP 600 SERIES
INSULATED WALL PANEL CONNECTION TO SLAB
WITH THERMAL BREAK & 2 CURBS